## **CONARGO FEEDLOT**

## **EPA MONITORING REQUIREMENTS**

Date of Sampling & Testing: 13 JUNE 2019

POLLUTANT	UNIT	MONITORING SITE 1	MONITORING SITE 2
Ammonia, as N - NH3 as N (DA)	Mg N/L	<0.1	1.1
Electrical Conductivity @ 25C - EC	u\$/cm	5200	2100
Nitrate, as N - NO3-N	Mg N/L	0.68	0.17
Н	Units	7.3	7.5
Standing Water Level	Metres (AHD)	85.006	86.451

Monitoring Site 1 ~ Monitoring bore, located in the south eastern end of feedlot. Monitoring Site 2 ~ Monitoring bore, located in the south western end of feedlot.

Sample testing conducted by ALS Water, Bendigo Laboratory